

EZ-View Change List

Version	Change Description
1.1.5	Modified EZ-Tap Driver to fix negative timestamps and prevent DCE/DTE data “lockout” that could occur under certain circumstances. Improved time tagging algorithm is much more accurate, especially when monitoring full-duplex communication
1.1.6	Fixed a buffer overflow problem that occurred at baud rates of 57600 and 115200 when monitoring long or continuous data streams